



## **DL.2 v1.0.1 Release Notes**

September 29, 2005

DL.2 v1.0.1 is a small maintenance release for fixtures that shipped early with v1.0.0 to select customers. All fixtures are currently shipping with v1.0.1 software.

There are two software components, the Content Management Application (CMA) Client and the .dl2 upgrade package for the fixture itself. Installation of the latest CMA Client Software should always be done prior to initiating an upgrade of the fixture using the .dl2 package.

The current version of the User Manual along with the Software is available at:

[http://www.highend.com/support/digital\\_lighting/dl2.asp](http://www.highend.com/support/digital_lighting/dl2.asp)

Users with access to DL.2 fixtures that are interested in joining the Software Testing Program may apply to become Beta Testers at:

<http://digital.highend.com/library/betasignup.nsf/request>

After updating, the Versions reported should be:

- *Software Version:* 1.0.1.617
- *Firmware Version:* 1.0.1.11
- *Windows XPe:* 1.0.1 or 1.0.0

### **Known Issues in v1.0.1:**

- When doing a Graphics Engine Reboot from DMX, there is a 2 minute delay in shutting down Windows to restart (#7758)
- Using Factory Defaults followed by a Power cycle/Home may initiate a Firmware upgrade, users are encouraged to not set the Factory Defaults field at this time (#7937).
- Error and Warning messages not yet implemented. Basic Status information available in Menu at Info->Status (#7590).
- Global Clock Sync not functioning (#7653).
- Images can be slow to load the very first time they are called up, especially with multiple layers running (#7760).
- Fixture/Lamp Hour Resets not functioning properly (#6789).
- Rapid changing of images/videos for hours causes memory leak (#7660).
- Deploying Large Content Archives ~8GB or Archives with individual files >1GB may fail (#6407)
- Sync modes not fully implemented (#7245).

## Bugs Fixed in v1.0.1:

- 7857 Fixed Motion Home All from causing Pan/Tilt to slam into stops occasionally.
- 7904 Client Installer now defaults to 'Program Files' location
- 7867 Security failure message added to display.
- 7912 Setting Fixture ID to 0 from CMA causes fixture not to boot
- 7859 CMA/Menu Setting inconsistencies fixed.
- 7910 Tilt motors misstepping fixed.
- 7913 Raw Data in DMX Menu Display now shows first entry for 'channel 0' as '--'
- 7614 Fixed occasional Menu lock ups
- 7822 Fixed Tilt Switch Auto not functioning and/or conflicts w/ registry
- 7868 Iris closes on loss of USB Comm
- 7920 Projector Defaults Menu Lockup fixed.
- 7923 Added 'Select All' and 'Clear All' buttons in CMA Upgrade Wizard
- 7917 DL-2 would not boot with video test pattern to "2"
- 7843 Added 30 second wait after menu keypress before enabling Preview on display.
- 7866 Fixed Security false triggering
- 7927 Data Loss Timeout: 'Off' option removed
- 7890 Projector Defaults sent to Projector
- 7655 Display Default: Left/Right Nav buttons improved
- 7900 Menu w/Invert On was partially off top of screen
- 7621 Fixture Shutdown' behaviour improved
- 6776 Fixed DL-2 position loss after being bumped
- 7566 projector input gets lost, must hard reset to rectify resolved.
- 7772 iris remains closed even when GE running fixed.
- 7862 Fixture should wake up on connecting DMX data after dataloss timeout
- 7532 Lamp/Projector Startup Modes implemented
- 7905 CMA Client Installer needs a EULA
- 6816 Pan and tilt slow just before hitting destination
- 7907 DL-2 loses position after homing
- 7787 Display Auto-invert occasionally not auto inverting
- 7799 iris slightly open upon bootup fixed
- 7932 Menu Button hits/Tilt Switch delays Data Loss Shutdown from happening
- 7560 Pan/Tilt Encoder On/Off setting in menu does nothing
- 7924 Iris closing for loss of USB comm to trimmed to 2 to 4 seconds
- 7914 CMA allows for invalid value for Self Test Video Pattern
- 7903 Chroma effects go away when image pos is not default